

**FAC 7344      Postal Facility**

RUC:            \$120.44 SF

Source:        Composite of other FACs/CATCODES  
In V12, Tri-Service and USACE PAX Newsletter values were updated while all other values were inflated only.

SUC:            \$3.50 SF

Source:        Cost Works model in \$FY-08, inflated to \$FY-09 using Green Book  
Table 5-6 (O&M less DHP)  
In V12, values were inflated only.

Model follows:

Chart:        A chart showing relative annual sustainment requirements appears  
below:

**FAC 7344-Postal Facility**  
**CostWorks 2008 Quarter 2**

Design Life= 50  
Average S.F= 3,485

C.S.F=100 S.F; MSF=1000 S.F  
Sq=100 S.F; M.L.F=1000 L.F

This spreadsheet was  
exported from R.S Means  
CostWorks

Terminal Cutoff is the removal of a single task occurrence if that task occurs  
within 10% of the end of the design life and if the frequency of the task exceeds  
20% of the design life. This prevents scheduling major work near the end of the  
design life

Description	Frequency	Crew	Qty	Unit	Total In-House	Total Incl. O&P	Release	Occurrences in Design Life	Adjusted Occurrences	Terminal Cutoff
Repair brick wall - 1st floor	25	1 Bric	49.400	S.F.	1,827.80	2,221.02	2008 Qtr 2	2	1	\$ 2,221.02
Replace brick wall - 2nd floor	75	2 Bric	4.940	C.S.F.	10,105.21	12,125.67	2008 Qtr 2	0	0	\$ -
Repair 8" concrete block wall - 1st floor	25	1 Bric	184.200	S.F.	3,695.05	4,494.48	2008 Qtr 2	2	1	\$ 4,494.48
Replace 8" concrete block wall - 1st floor	60	2 Bric	18.420	C.S.F.	18,325.51	22,059.24	2008 Qtr 2	0	0	\$ -
Replace 8" concrete block wall - 2nd floor	60	2 Bric	17.070	C.S.F.	18,114.17	21,824.00	2008 Qtr 2	0	0	\$ -
Repair 2'-0" x 3'-0" aluminum window - 1st floor	20	1 Carp	3.200	Ea.	367.87	435.84	2008 Qtr 2	2	2	\$ 871.68
Replace 2'-0" x 3'-0" aluminum window - 1st floor	50	1 Carp	32.000	Ea.	14,035.20	16,415.68	2008 Qtr 2	1	0	\$ -
Replace glass - 1st floor (1% of glass)	1	1 Carp	1.920	S.F.	17.38	20.39	2008 Qtr 2	50	50	\$ 1,019.52
Replace glass - 2nd floor (1% of glass)	1	1 Carp	1.920	S.F.	167.81	205.54	2008 Qtr 2	50	50	\$ 10,276.80
Repair 2'-0" x 3'-0" aluminum window - 2nd floor	20	1 Carp	3.200	Ea.	491.84	590.14	2008 Qtr 2	2	2	\$ 1,180.29
Replace 2'-0" x 3'-0" aluminum window - 2nd floor	50	1 Carp	32.000	Ea.	15,275.20	17,958.72	2008 Qtr 2	1	0	\$ -
Repair 12' x 12' steel roll-up door	10	1 Carp	0.200	Ea.	166.52	192.91	2008 Qtr 2	5	5	\$ 964.54
Refinish 12' x 12' steel roll-up door	5	1 Pord	2.000	Ea.	337.66	411.08	2008 Qtr 2	10	10	\$ 4,110.80
Replace 12' x 12' steel roll-up door	35	2 Carp	2.000	Ea.	6,650.54	7,699.10	2008 Qtr 2	1	1	\$ 7,699.10
Prepare and refinish 3'-0" x 7'-0" steel ptd. door	4	1 Pord	1.000	Ea.	65.21	80.74	2008 Qtr 2	12	12	\$ 968.88
Replace 3'-0" x 7'-0" steel, w/ wire glass, ptd. door	45	1 Carp	1.000	Ea.	939.96	1,095.60	2008 Qtr 2	1	1	\$ 1,095.60
Replace tempered glass - (3% of glass)	1	1 Carp	0.630	S.F.	12.16	14.46	2008 Qtr 2	50	50	\$ 723.24
Repair steel, painted, door	14	1 Carp	0.300	Ea.	174.73	205.91	2008 Qtr 2	3	3	\$ 617.72
Refinish 3'-0" x 7'-0" steel, painted, door	4	1 Pord	3.000	Ea.	98.73	120.93	2008 Qtr 2	12	12	\$ 1,451.16
Replace 3'-0" x 7'-0" steel, painted, door	45	1 Carp	3.000	Ea.	1,596.24	1,860.12	2008 Qtr 2	1	1	\$ 1,860.12
Debris removal and visual inspection built-up roofing	0.5	2 Rofc	2.265	M.S.F.	66.46	80.07	2008 Qtr 2	100	100	\$ 8,006.78
Non-destructive moisture inspection built-up roofing	5	2 Rofc	2.265	M.S.F.	205.62	248.70	2008 Qtr 2	10	10	\$ 2,486.97
Total roof replacement built-up roofing	28	G1	22.650	Sq.	12,928.17	15,310.27	2008 Qtr 2	1	1	\$ 15,310.27
Minor membrane repairs - (2% of roof area) built-up roofing	5	G5	0.453	Sq.	156.07	184.39	2008 Qtr 2	10	10	\$ 1,843.89
Flashing repairs - (2 S.F. per sq. repaired) built-up roofing	5	2 Rofc	0.906	S.F.	3.04	3.62	2008 Qtr 2	10	10	\$ 36.24
Minor membrane replacement - (25% of roof area) built-up roofing	20	G5	5.663	Sq.	3,366.26	4,015.52	2008 Qtr 2	2	2	\$ 8,031.04
Debris removal by hand & visual inspection,modified bitum/thermoplastc	1	2 Rofc	0.610	M.S.F.	17.90	21.56	2008 Qtr 2	50	50	\$ 1,078.18
Non-destructive moisture inspection,modified bitum/thermoplastic	5	2 Rofc	0.610	M.S.F.	55.38	66.98	2008 Qtr 2	10	10	\$ 669.78
Total roof replacement,modified bituminous / thermoplastic	25	G1	6.100	Sq.	2,969.72	3,510.61	2008 Qtr 2	2	1	\$ 3,510.61
Minor membrane repairs-(2% of roof area),modified bitum/thermoplastic	5	G5	0.122	Sq.	32.55	38.40	2008 Qtr 2	10	10	\$ 383.98
Flashing repairs-(2 S.F. per sq. repaired),modified bitum/thermoplastc	5	2 Rofc	0.244	S.F.	0.81	0.95	2008 Qtr 2	10	10	\$ 9.54
Membrane replacement-(25% of roof area),modified bitum/thermoplastic	20	G5	1.525	Sq.	971.04	1,151.22	2008 Qtr 2	2	2	\$ 2,302.45
Repair steel painted interior door	14	1 Carp	0.200	Ea.	33.55	39.63	2008 Qtr 2	3	3	\$ 118.88
Refinish 3'-0" x 7'-0" steel painted interior door	4	1 Pord	2.000	Ea.	98.80	121.64	2008 Qtr 2	12	12	\$ 1,459.68
Replace 3'-0" x 7'-0" steel painted interior door	60	1 Carp	2.000	Ea.	1,875.08	2,179.92	2008 Qtr 2	0	0	\$ -
Repair solid core wood door interior	11	1 Carp	1.600	Ea.	268.40	317.02	2008 Qtr 2	4	4	\$ 1,268.10

**FAC 7344-Postal Facility**  
**CostWorks 2008 Quarter 2**

Design Life= 50  
Average S.F= 3,485

C.S.F=100 S.F; MSF=1000 S.F  
Sq=100 S.F; M.L.F=1000 L.F

This spreadsheet was  
exported from R.S Means  
CostWorks

Terminal Cutoff is the removal of a single task occurrence if that task occurs  
within 10% of the end of the design life and if the frequency of the task exceeds  
20% of the design life. This prevents scheduling major work near the end of the  
design life

Description	Frequency	Crew	Qty	Unit	Total In-House	Total Incl. O&P	Release	Occurrences in Design Life	Adjusted Occurrences	Terminal Cutoff
Refinish 3'-0" x 7'-0" solid core wood door interior	4	1 Pord	16.000	Ea.	675.52	831.68	2008 Qtr 2	12	12	\$ 9,980.16
Replace 3'-0" x 7'-0" solid core wood door interior	40	1 Carp	16.000	Ea.	5,867.20	6,801.92	2008 Qtr 2	1	1	\$ 6,801.92
Repair concrete steps	15	1 Cefi	0.900	S.F.	15.29	17.80	2008 Qtr 2	3	3	\$ 53.41
Replace concrete steps	100	2 Cefi	9.000	S.F.	445.59	540.81	2008 Qtr 2	0	0	\$ -
Replace metal stair railing interior	45	2 Sswk	11.000	L.F.	394.57	455.84	2008 Qtr 2	1	1	\$ 455.84
Repair fabric wall finish fabric interior	9	1 Pord	105.800	S.Y.	2,665.10	3,227.96	2008 Qtr 2	5	5	\$ 16,139.79
Replace fabric wall finish fabric interior	50	1 Pord	105.800	S.Y.	14,868.07	18,140.47	2008 Qtr 2	1	0	\$ -
Refinish drywall	12	1 Pord	6,083.000	S.F.	3,649.80	4,501.42	2008 Qtr 2	4	3	\$ 13,504.26
Replace 5/8" drywall	75	2 Carp	6,083.000	S.F.	13,565.09	16,363.27	2008 Qtr 2	0	0	\$ -
Repair 5/8" drywall - (2% of walls)	20	1 Carp	121.700	S.F.	193.50	232.45	2008 Qtr 2	2	2	\$ 464.89
Replace carpet	12	2 Tilf	121.800	S.Y.	5,496.83	6,350.65	2008 Qtr 2	4	3	\$ 19,051.96
Refinish concrete floor finished	25	2 Cefi	21.090	C.S.F.	7,369.69	8,872.35	2008 Qtr 2	2	1	\$ 8,872.35
Replace terrazzo floor	75	2 Mstz	1.650	C.S.F.	2,375.90	2,813.70	2008 Qtr 2	0	0	\$ -
Terrazzo floor repairs - (2% of floors)	15	1 Mstz	3.300	S.F.	49.57	59.20	2008 Qtr 2	3	3	\$ 177.61
Replace vinyl floor	18	1 Tilf	0.128	S.Y.	6.11	7.46	2008 Qtr 2	2	2	\$ 14.92
Replace acoustic tile ceiling, fire-rated	20	1 Carp	12.910	C.S.F.	5,204.67	6,183.89	2008 Qtr 2	2	2	\$ 12,367.78
Refinish sheetrock ceiling	20	1 Pord	1.950	C.S.F.	245.06	302.82	2008 Qtr 2	2	2	\$ 605.63
Replace sheetrock ceiling	40	2 Carp	1.950	C.S.F.	698.74	853.14	2008 Qtr 2	1	1	\$ 853.14
Repair sheetrock ceiling - (2% of ceilings)	20	1 Carp	0.039	C.S.F.	13.62	16.62	2008 Qtr 2	2	2	\$ 33.25
Check / minor repairs drinking fountain	1	1 Plum	1.000	Ea.	37.58	47.34	2008 Qtr 2	50	50	\$ 2,367.00
Repair internal leaks drinking fountain	4	1 Plum	1.000	Ea.	35.14	43.43	2008 Qtr 2	12	12	\$ 521.16
Correct water pressure drinking fountain	2	1 Plum	1.000	Ea.	32.21	40.50	2008 Qtr 2	25	25	\$ 1,012.50
Replace refrigerant drinking fountain	2	1 Plum	1.000	Ea.	15.84	18.86	2008 Qtr 2	25	25	\$ 471.50
Repair drain leak drinking fountain	4	1 Plum	1.000	Ea.	22.63	27.03	2008 Qtr 2	12	12	\$ 324.36
Replace fountain drinking fountain	10	2 Plum	1.000	Ea.	1,005.84	1,193.57	2008 Qtr 2	5	5	\$ 5,967.85
Replace washer in spud connection lavatory, vitreous china	7	1 Plum	7.000	Ea.	168.07	198.31	2008 Qtr 2	7	7	\$ 1,388.17
Replace washer in faucet lavatory, vitreous china	2	1 Plum	7.000	Ea.	68.95	86.03	2008 Qtr 2	25	25	\$ 2,150.75
Replace faucets lavatory, vitreous china	10	1 Plum	7.000	Ea.	864.43	1,043.42	2008 Qtr 2	5	5	\$ 5,217.10
Clean out strainer and P trap lavatory, vitreous china	2	1 Plum	7.000	Ea.	189.28	234.99	2008 Qtr 2	25	25	\$ 5,874.75
Replace lavatory, vitreous china	35	2 Plum	7.000	Ea.	3,711.33	4,449.90	2008 Qtr 2	1	1	\$ 4,449.90
Replace faucet washer sink, iron enamel	2	1 Plum	1.000	Ea.	9.79	12.19	2008 Qtr 2	25	25	\$ 304.75
Clean trap sink, iron enamel	3	1 Plum	1.000	Ea.	6.60	8.25	2008 Qtr 2	16	16	\$ 132.00
Replace faucets sink, iron enamel	10	1 Plum	1.000	Ea.	123.49	149.06	2008 Qtr 2	5	5	\$ 745.30
Unstop sink sink, iron enamel	2	1 Plum	1.000	Ea.	32.21	40.50	2008 Qtr 2	25	25	\$ 1,012.50
Replace sink, P.E.C.I. sink, iron enamel	35	2 Plum	1.000	Ea.	552.72	657.69	2008 Qtr 2	1	1	\$ 657.69
Replace flush valve diaphragm tankless water closet	10	1 Plum	5.000	Ea.	353.70	415.30	2008 Qtr 2	5	5	\$ 2,076.50

**FAC 7344-Postal Facility**  
**CostWorks 2008 Quarter 2**

Design Life= 50  
Average S.F= 3,485

C.S.F=100 S.F; MSF=1000 S.F  
Sq=100 S.F; M.L.F=1000 L.F

This spreadsheet was  
exported from R.S Means  
CostWorks

Terminal Cutoff is the removal of a single task occurrence if that task occurs  
within 10% of the end of the design life and if the frequency of the task exceeds  
20% of the design life. This prevents scheduling major work near the end of the  
design life

Description	Frequency	Crew	Qty	Unit	Total In-House	Total Incl. O&P	Release	Occurrences in Design Life	Adjusted Occurrences	Terminal Cutoff
Rebuild flush valve tankless water closet	20	1 Plum	5.000	Ea.	659.90	800.05	2008 Qtr 2	2	2	\$ 1,600.10
Unplug clogged line tankless water closet	5	1 Plum	5.000	Ea.	841.30	1,050.90	2008 Qtr 2	10	10	\$ 10,509.00
Replace tankless water closet	35	2 Plum	5.000	Ea.	2,740.00	3,241.80	2008 Qtr 2	1	1	\$ 3,241.80
Replace tankless flush valve	25	1 Plum	5.000	Ea.	1,047.50	1,226.85	2008 Qtr 2	2	1	\$ 1,226.85
Replace wax ring gasket tankless water closet	5	1 Plum	5.000	Ea.	547.85	686.00	2008 Qtr 2	10	10	\$ 6,860.00
Replace flush valve diaphragm urinal	7	1 Plum	2.000	Ea.	141.48	166.12	2008 Qtr 2	7	7	\$ 1,162.84
Rebuild flush valve urinal	20	1 Plum	2.000	Ea.	263.96	320.02	2008 Qtr 2	2	2	\$ 640.04
Unplug line urinal	5	1 Plum	2.000	Ea.	224.28	279.82	2008 Qtr 2	10	10	\$ 2,798.20
Replace wall-hung urinal	35	2 Plum	2.000	Ea.	1,683.26	2,013.14	2008 Qtr 2	1	1	\$ 2,013.14
Inspect / check pump / motor operation, lub. circulation pump, 1/12 HP	0.5	1 Plum	1.000	Ea.	6.19	7.72	2008 Qtr 2	100	100	\$ 772.00
Replace pump / motor assembly circulation pump, 1/12 HP	10	2 Plum	1.000	Ea.	736.33	863.29	2008 Qtr 2	5	5	\$ 4,316.45
Resolder joint pipe & fittings, copper	10	1 Plum	1.000	Ea.	32.85	40.45	2008 Qtr 2	5	5	\$ 202.25
Replace pipe and fittings, copper 3/4"	20	2 Plum	16.000	L.F.	283.52	343.68	2008 Qtr 2	2	2	\$ 687.36
Replace pipe and fittings, copper 2"	25	2 Plum	8.000	L.F.	326.48	392.88	2008 Qtr 2	2	1	\$ 392.88
Remove old insulation & replace with new, pipe 3/4", wall 1"	15	1 Plum	16.000	L.F.	112.16	136.64	2008 Qtr 2	3	3	\$ 409.92
Drain and flush water heater, electric, 120 gallon	7	1 Plum	0.500	Ea.	113.22	141.52	2008 Qtr 2	7	7	\$ 990.64
Check operation water heater, electric, 120 gallon	3	1 Plum	0.500	Ea.	0.99	1.24	2008 Qtr 2	16	16	\$ 19.84
Replace water heater, electric, 120 gallon	15	2 Plum	0.500	Ea.	4,596.23	5,271.90	2008 Qtr 2	3	3	\$ 15,815.69
Unclog main drain pipe & fittings, cast iron	10	1 Plum	1.000	Ea.	35.62	44.41	2008 Qtr 2	5	5	\$ 222.05
Replace pipe & fittings, cast iron	40	2 Plum	8.000	L.F.	335.20	405.60	2008 Qtr 2	1	1	\$ 405.60
Unclog floor drain, PVC	20	1 Plum	1.000	Ea.	37.09	45.87	2008 Qtr 2	2	2	\$ 91.74
Repair joint pipe and fittings, PVC	10	1 Plum	1.000	Ea.	115.94	144.14	2008 Qtr 2	5	5	\$ 720.70
Replace pipe, 4" pipe and fittings, PVC	30	2 Plum	8.000	L.F.	473.60	585.52	2008 Qtr 2	1	1	\$ 585.52
General maintenance & repair drain: roof, scupper, area	1	1 Plum	1.000	Ea.	28.35	35.67	2008 Qtr 2	50	50	\$ 1,783.50
Replace drain: roof, scupper, area	40	1 Plum	1.000	Ea.	398.34	468.14	2008 Qtr 2	1	1	\$ 468.14
Replace fan & motor, propeller exh., 4700 CFM exhaust fan	15	Q20	1.000	Ea.	1,393.63	1,626.35	2008 Qtr 2	3	3	\$ 4,879.05
Repair single zone rt. unit, 5 ton	10	2 Stpi	0.500	Ea.	964.86	1,157.28	2008 Qtr 2	5	5	\$ 5,786.40
Replace single zone rt. unit, 5 ton	15	Q5	1.000	Ea.	7,276.88	8,588.60	2008 Qtr 2	3	3	\$ 25,765.80
Repair fan coil unit, 1 ton	10	1 Stpi	0.500	Ea.	184.61	220.51	2008 Qtr 2	5	5	\$ 1,102.55
Replace fan coil unit, 1 ton	15	Q5	1.000	Ea.	1,098.30	1,295.56	2008 Qtr 2	3	3	\$ 3,886.68
Replace fire alarm bell, 6"	20	1 Elec	2.000	Ea.	284.56	343.02	2008 Qtr 2	2	2	\$ 686.04
Minor repairs to fire alarm control panel	5	1 Elec	1.000	Ea.	107.84	130.97	2008 Qtr 2	10	10	\$ 1,309.70
Maintenance and inspection fire alarm control panel	0.5	1 Elec	1.000	Ea.	30.54	38.17	2008 Qtr 2	100	100	\$ 3,817.00
Replace fire alarm control panel	15	1 Elec	1.000	Ea.	2,615.62	3,107.84	2008 Qtr 2	3	3	\$ 9,323.52
Replace sprinkler head	20	1 Plum	30.000	Ea.	1,910.40	2,353.80	2008 Qtr 2	2	2	\$ 4,707.60
Inspect sprinkler system	1	1 Plum	1.000	Ea.	26.55	32.89	2008 Qtr 2	50	50	\$ 1,644.50

**FAC 7344-Postal Facility**  
**CostWorks 2008 Quarter 2**

Design Life= 50  
Average S.F= 3,485

C.S.F=100 S.F; MSF=1000 S.F  
Sq=100 S.F; M.L.F=1000 L.F

This spreadsheet was  
exported from R.S Means  
CostWorks

Terminal Cutoff is the removal of a single task occurrence if that task occurs  
within 10% of the end of the design life and if the frequency of the task exceeds  
20% of the design life. This prevents scheduling major work near the end of the  
design life

Description	Frequency	Crew	Qty	Unit	Total In-House	Total Incl. O&P	Release	Occurrences in Design Life	Adjusted Occurrences	Terminal Cutoff
Rebuild double check 3" backflow preventer sprinkler system	5	1 Plum	1.000	Ea.	598.06	715.83	2008 Qtr 2	10	10	\$ 7,158.30
Repair failed breaker, 3 pole circuit breaker	10	1 Elec	1.000	Ea.	342.23	400.69	2008 Qtr 2	5	5	\$ 2,003.45
Maintenance and inspection C.B., 3 pole circuit breaker	0.33	1 Elec	1.000	Ea.	22.91	28.50	2008 Qtr 2	151	151	\$ 4,303.50
Replace C.B. molded case, 600 V, 3 pole circuit breaker	50	1 Elec	1.000	Ea.	3,157.74	3,611.55	2008 Qtr 2	1	0	\$ -
Maintenance and inspection lighting panel, indoor	3	1 Elec	1.000	Ea.	28.50	35.63	2008 Qtr 2	16	16	\$ 570.08
Replace fluor. ballast for fluorescent lighting fixture, 80 W	10	1 Elec	34.000	Ea.	3,385.72	4,082.72	2008 Qtr 2	5	5	\$ 20,413.60
Replace lamps (2 lamps) fluorescent lighting fixture, 80 W	10	1 Elec	34.000	Ea.	864.96	1,060.12	2008 Qtr 2	5	5	\$ 5,300.60
Maintenance and repair incandescent lighting fixtures	10	1 Elec	2.000	Ea.	94.56	112.78	2008 Qtr 2	5	5	\$ 563.90
Replace lamp incandescent lighting fixtures	5	1 Elec	2.000	Ea.	13.96	17.04	2008 Qtr 2	10	10	\$ 170.40
Maintenance and repair receptacles and plugs	20	1 Elec	100.000	Ea.	3,109.00	3,873.00	2008 Qtr 2	2	2	\$ 7,746.00
Replace receptacle/plug receptacles and plugs	20	1 Elec	100.000	Ea.	5,276.00	6,442.00	2008 Qtr 2	2	2	\$ 12,884.00
Maintenance and repair wiring devices, switches	10	1 Elec	56.000	Ea.	1,741.04	2,168.88	2008 Qtr 2	5	5	\$ 10,844.40
Replace switch wiring devices, switches	15	1 Elec	56.000	Ea.	2,867.76	3,491.60	2008 Qtr 2	3	3	\$ 10,474.80
Check and repair manual pull station	10	1 Elec	3.000	Ea.	207.63	254.61	2008 Qtr 2	5	5	\$ 1,273.05
Replace manual pull station	15	1 Elec	3.000	Ea.	377.22	455.67	2008 Qtr 2	3	3	\$ 1,367.01
Repair smoke detector	10	1 Elec	7.000	Ea.	267.33	329.00	2008 Qtr 2	5	5	\$ 1,645.00
Check operation smoke detector	1	1 Elec	7.000	Ea.	79.80	100.10	2008 Qtr 2	50	50	\$ 5,005.00
Replace smoke detector	15	1 Elec	7.000	Ea.	1,326.85	1,588.93	2008 Qtr 2	3	3	\$ 4,766.79

**\$241,980.05      \$288,938.91**

MR Subtotal    \$ 427,456.99

MR Per Year    \$    8,549.14

PM Per Year    \$    4,037.03

Subtotal        \$ 12,586.17

Total Per Unit    \$        3.61

**CostWorks 2009 Quarter 1 - FAC 7344-Postal Facility**

Qty	Assembly Number	Description	Total In-House	Total Incl. O&P	Zip Code Prefix	Type	Release
2.000	B2035 410 1950	Door, overhead, electric, roll up, to 24' high x 25' w	480.32	580.24	200	FMR	2008 Qtr 2
20.000	B2035 225 1950	Door, emergency egress, swinging, annualized	990.20	1,150.20	200	FMR	2008 Qtr 2
2.000	C1025 110 1950	Fire doors, swinging, annualized	49.78	59.72	200	FMR	2008 Qtr 2
2.000	D2015 100 1950	Urinals, annualized	25.86	32.30	200	FMR	2008 Qtr 2
5.000	D2015 100 2950	Toilet (vacuum breaker type), annualized	64.65	80.75	200	FMR	2008 Qtr 2
7.000	D2015 100 4950	Lavatories, annualized	172.76	210.56	200	FMR	2008 Qtr 2
1.000	D2015 800 1950	Drink fountain, annualized	49.50	59.36	200	FMR	2008 Qtr 2
1.000	D3045 120 1950	Fan coil unit, annualized	215.71	266.60	200	FMR	2008 Qtr 2
2.000	D3045 160 1950	VAV Boxes, annualized	122.62	152.00	200	FMR	2008 Qtr 2
1.000	D3045 210 1950	Fan, axial, up to 5,000 CFM, annualized	70.55	86.20	200	FMR	2008 Qtr 2
1.000	D3055 210 1950	Package unit, air cooled, 3 thru 24 ton, annualized	207.71	251.03	200	FMR	2008 Qtr 2
1.000	D4015 100 1950	Backflow prevention device, up to 4", annualized	18.89	23.42	200	FMR	2008 Qtr 2
1.000	D4015 150 1950	Extinguishing system, wet pipe, annualized	806.79	983.35	200	FMR	2008 Qtr 2
1.000	D5015 220 1950	Circuit breaker, high voltage air, annualized	26.98	33.59	200	FMR	2008 Qtr 2
1.000	D5015 260 1950	Panelboard, 225 A and above, annualized	56.96	67.71	200	FMR	2008 Qtr 2
			<b>\$3,359.28</b>	<b>\$4,037.03</b>			



FAC 7344 Sustainment by Year - Terminal Cutoff Applied

